

HABS
VI,
2-MABA,
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Estate Annaberg
St. John Island
Virgin Islands

HABS No. VI-18

Frederik C. Gjessing, Photographer November, 1959

- VI-18-1 GENERAL VIEW OF SITE FROM NORTHWEST, MILL TOWER SHOWING
- VI-18-2 VILLAGE RUINS FROM SOUTHEAST, MARY POINT IN BACKGROUND
- VI-18-3 VILLAGE RUINS IN FOREGROUND, FACTORY BEHIND, FROM NORTHWEST
- VI-18-4 GENERAL VIEW FROM WEST; HORSE MILL TO LEFT, MILL TOWER, BOILING HOUSE IN CENTER, STORAGE AND CURING HOUSE TO RIGHT
- VI-18-5 CURING AND STORAGE HOUSE FROM SOUTH, HORSE MILL, MILL TOWER IN BACKGROUND
- VI-18-6 CURING AND STORAGE HOUSE, STORAGE WING FROM SOUTH, STABLE RUINS IN FOREGROUND
- VI-18-7 CURING AND STORAGE HOUSE, DETAIL OF DOORWAY
- VI-18-8 BOILING HOUSE FROM NORTHWEST, HORSE MILL IN LEFT FOREGROUND
- VI-18-9 BOILING HOUSE FROM MILL TOWER (NORTHEAST)
- VI-18-10 BOILING HOUSE, DETAIL OF WINDOW ON EAST WALL
- VI-18-11 STILL CISTERN, FROM SOUTH, HORSE MILL IN BACKGROUND
- VI-18-12 HORSE MILL FROM NORTHWEST (Note the three building stages of the platform. Wooden structure and cookhouse are of relatively recent dates.)
- VI-18-13 BAKE OVER, FROM WEST
- VI-18-14 ENTRANCE TO VAULT BELOW SOUTHEAST CORNER OF MILL PLATFORM, VIEWED FROM SOUTHWEST